

Plane malfunction warning

Owners of the Collins-type CIR-11() Emergency Locator Transmitter (ELT) have been cautioned by the FAA that unless properly armed, the ELTs could malfunction when needed.

Pilots owning this type of ELT were urged to obtain and retain an updated copy of the owner's manual issued March 20, 1981 by the Collins General Aviation Division of Rockwell International.